



Home

View

Help



Toggle left pane



New mail
New

Ignore
Report
Block



Delete
Delete



Reply
Respond



Sweep



Move to
Move



Rules



Read / Unread



Categorize



Flag / Unflag
Tags



Pin Unf



> Favorites

X Close

Previous

Next



> Folders

Re: TH-2301-41AL Inspection Results

Inbox

Junk Email 7

Drafts

Sent Items

Deleted Items 17

Archive

Notes 1

RSS Feeds

Create new fol...

You replied on Mon 2/6/2023 6:26 PM

TH

Travis Howell

To: You

Cc: Peter Bagnall; Eden Serrano; Ashley Winn; Yr



Mon 2/6/2023 5:15 PM



TH-2301-41AL Report_LAB.pdf

NOTICE ACCOMPANYING 2/2/23 HAZMAT INSPECTION REPORT.

2 attachments (3 MB) Save all to OneDrive Download all

> Groups

This report was supplemental to the original Report. The findings in the original report are still viable. We only performed Asbestos testing on the other materials/areas previously not sampled. So in short the ductwork is still positive as mentioned in 2018 report.

For the lead. As so long as your firm is EPA RRP certified you should be fine painting over lead based surfaces. If your planning on a full removal or more permanent option for the lead based paints then a lead abatement contractor would be more needed.

Sent from my iPhone

On Feb 6, 2023, at 4:58 PM, Frank Dickinson <frank_dickinson@hotmail.com> wrote:

Travis,

Thanks for getting out to the site and doing the Hazmat reports so quickly. I saw on the Asbestos report that you found none that needed to be remediated. At one